

Date:

2024/12/11

Report Type:

Maintenance

Customer:

| | |
|-----------------------------|----------------------|
| Name: <u>Dr. Zana Abbas</u> | Location: <u>sal</u> |
|-----------------------------|----------------------|

Machine:

| | |
|--|-------------------|
| Name: <u>HR</u> <input type="checkbox"/> | Type: <u>A 60</u> |
| Model: <u>motor Ax</u> | Serial No.: |

Inspection:

| | |
|---|---|
| Lamp shots: <u>332,530</u> | Conductivity: <u>1.3</u> |
| Rod shots: <u>16,623,172</u> | Lenses: <input checked="" type="checkbox"/> |
| Lamps No.: <u>4</u> | Main shape: <input checked="" type="checkbox"/> |
| Moveo use: <u>42</u> | Water leak: <input checked="" type="checkbox"/> |
| Photod.: External - Internal - | Electrical & Hydraulic parts: <u>α</u> |
| Results (phtod. & peltier)%: <u>1.7</u> | Power |
| Fiber test: <input checked="" type="checkbox"/> | |
| Alarms: <u>no Ax. Hp data</u> | After replacement: <u>-</u> |

Report:

HP data cable was changed

Actions:

I change the cable


Cost:

\$200 dis \$150

Engineer name & signature:



Customer Name & signature

Alward


Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square