

Date:

09.12.2024

Report Type:

Maintenance

Customer:

Name: center Pavilion	Location: sul
-----------------------	---------------

Machine:

Name: Motus Ax <input type="checkbox"/>	Type: Alexandrite
Model: M112 A1	Serial No.: QM0C272A

Inspection:

Lamp shots: 513079	Conductivity: 0.9 us
Rod shots: 6,614817	Lenses: ok
Lamps No.: 4	Main shape: ok
Moveo use: 0%	Water leak: ok
Photod.: External - Internal -	Electrical & Hydraulic parts: not ok
Results (phtod. & peltier)%:	Power Before replacement: —
Fiber test: ok	Power After replacement: —
Alarms: no Alarm	

Report:

HP cable was damaged

Actions:

I change HP cable


Cost:

8150

Engineer name & signature:



Customer Name & signature



Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square