

Date:

Report Type:

4.11.2024

Maintenance

Customer:

Name: Dr. Zana Abbas	Location: Sul -
----------------------	-----------------

Machine:

Name: Motus Ax <input type="checkbox"/>	Type: Alexandrite
Model: M112A1	Serial No.: QMOC179A

Inspection:

Lamp shots: 6,19,582	Conductivity: 1.845
Rod shots: 16,290,978	Lenses: no ok
Lamps No.: 3	Main shape: ok
Moveo use: 38%	Water leak: ok
Photod.: External 498 Internal 498	Electrical & Hydraulic parts: ok
Results (phtod. & peltier)%: 0.4	Power
Fiber test:	Before replacement: 27.1 = 540 J
Alarms: low energy	After replacement: 30.6 = 475 J

Report:

- lens III was damaged
- low energy more than two times
- The lens was dirty

Actions:

- I change fresh lamp and clean the lens
- I change lens III

Cost: \$2000 + \$225 = \$2225

Engineer name & signature:

Customer Name & signature

Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square