

Date:

2024/11/04

Report Type:

maintenance check

Customer:

Name: Dr. Hazem	Location: sul
-----------------	---------------

Machine:

Name: Hair Remover <input type="checkbox"/>	Type: A lux
Model: motor A	Serial No.:

Inspection:

Lamp shots: 2,454,496	Conductivity: 1,1	
Rod shots: 9,736,276	Lenses: x	
Lamps No.: 4	Main shape: ✓	
Moveo use: 37	Water leak: ✓	
Photod.: External 49J Internal 49J	Electrical & Hydraulic parts: ✓	
Results (phtod. & peltier)%: 0.0%	Power	
Fiber test: ✓		Before replacement: 30,6-542
		After replacement: 30,6-480
Alarms: low Energy		

Report:


- low power
- Three lens was damaged (141 + 141)

Actions:

- I change the flash lamp
- I change the lens 141:2, 141:1

Cost: ^{Flash} 82000 + ^{lens} 8675 = 82675

Engineer name & signature:



Customer Name & signature



Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square