

Date:

2024/11/9

Report Type:

maintan
~~check~~

Customer:

Name: <u>Dr. Doshan</u>	Location: <u>sul</u>
-------------------------	----------------------

Machine:

Name: <u>Hair Remov</u> <input type="checkbox"/>	Type: <u>Alex</u>
Model: <u>matu, Ax</u>	Serial No.: <u>QMOC 364A</u>

Inspection:

Lamp shots: <u>4,924,639</u>	Conductivity: <u>0.7 MS</u>
Rod shots: <u>15,963,647</u>	Lenses: <input checked="" type="checkbox"/>
Lamps No.: <u>3</u>	Main shape: <input checked="" type="checkbox"/>
Moveo use: <u>24%</u>	Water leak: <input checked="" type="checkbox"/>
Photod.: External <input type="checkbox"/> Internal <input type="checkbox"/>	Electrical & Hydraulic parts: <input checked="" type="checkbox"/>
Results (phtod. & peltier)%: <u>0.1 %</u>	Power
Fiber test: <u>ok</u>	
Alarms: <u>water level</u>	After replacement: <u>_____</u>

Report:

There was water leak from a connector


Actions:

I change the connector


Cost:

8350 dis 8300

Engineer name & signature:



Customer Name & signature



Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square