

Date: 16-12-2024

Report Type: Maintenance

Customer:

Name: Dr. Birvan	Location: Loya
------------------	----------------

Machine:

Name: motus AX <input checked="" type="checkbox"/>	Type: Alexandrite
Model: M112A1	Serial No.: QM0C183A

Inspection:

Lamp shots: 3,911,656	Conductivity: 8.1 uS
Rod shots: 4,463,3031	Lenses: not ok
Lamps No.: 6	Main shape: ok
Moveo use: 99%	Water leak: ok
Photod.: External - Internal -	Electrical & Hydraulic parts: ok
Results (phtod. & peltier)%: 7.3%	Power
Fiber test: ok	
Alarms: no Alarm	After replacement: -

Report:


sphire lens was damaged

Actions:

I change sphire lens

Cost: \$2200 ^{dis} → \$1900

Engineer name & signature:



Customer Name & signature



Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square

Senior Engineer: Siyamend Alsino, 07514343415 - 07828386448