

Date:

2025/1/11

Report Type:

Maintenance

**Customer:**

Name: Dr. Derac	Location: Sul
-----------------	---------------

**Machine:**

Name: H.R <input type="checkbox"/>	Type: A1ea
Model: motor Aa	Serial No.: QM9B248A

**Inspection:**

Lamp shots: 2066242	Conductivity: 6.0 M
Rod shots: 15.642067	Lenses: ✓
Lamps No.: 4	Main shape: on
Moveo use: 0 d/o	Water leak: not on
Photod.: External 498 Internal 498	Electrical & Hydraulic parts: on
Results (phtod. & peltier%): 1.9%	Before replacement: 27.555uo
Fiber test:	Power After replacement: 30.65485
Alarms: low Energy	

**Report:**

- The power was low
- There was water leak


**Actions:**

- I change the 2 lash lamp.
- I change one connector for water


**Cost:**

20000000

Engineer name & signature:



Customer Name & signature



Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square