

Date:

13-01-2025

Report Type:

Maintenance

**Customer:**

Name: Dr. Birvan	Location: Koya
------------------	----------------

**Machine:**

Name: Had Removed <input checked="" type="checkbox"/>	Type: Alexander
Model: M12A1	Serial No.:

**Inspection:**


Lamp shots: 5,132,498	Conductivity: 27 uS
Rod shots: 45,855,868	Lenses: OK
Lamps No.: 6	Main shape: OK
Moveo use: 99%	Water leak: not OK
Photod.: External - Internal -	Electrical & Hydraulic parts: OK
Results (phtod. & peltier)%: 1.9%	Power
Fiber test: OK	
Alarms: water level	After replacement: _____

**Report:**  
There was water leak from a connector

**Actions:**  
I change the connector

**Cost:** \$350 → \$300

Engineer name & signature:



Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Customer Name & signature



Main Office: Erbil, Mahmood Alhafeed Square