

Date:

16-11-2024

Report Type:

check

Customer:

Name: Dr. Sencer	Location: Sul
------------------	---------------

Machine:

Name: #Epicuro <input type="checkbox"/> 1	Type: Alexakrite
Model: Zenith	Serial No.: 504-23-819-2TAA

Inspection:


Lamp shots: 2006297	Conductivity: —
Rod shots: 3.488,863	Lenses: not on
Lamps No.: 2	Main shape: on
Moveo use: —	Water leak: on
Photod.: External on Internal on	Electrical & Hydraulic parts: on
Results (phtod. & peltier)%: —	Power
Fiber test: on	
	After replacement: —
Alarms: no Alarm	

Report: The fiber lens damaged
Actions: I change lens 504-1700-10
Cost: 8400 ^{dis} → 8360

Engineer name & signature:



Customer Name & signature



Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square