

Date:

05-12-2024

Report Type:

Maintenance

Customer:

Name: Bayshin Hospital	Location: Halabja
------------------------	-------------------

Machine & Inspection:

Name	Type	Model	Serial Number	Lamp Shoots	✓ / ✗
Coel	Coeluser	smuxel	ISM X230601636	-	✓
microwell RF	RF	Ashley	ASH 2011 0018	-	✓
Hydrofacial	suction	PDT	16519111723	-	✓
Q-switch	ndiyag	Q-10	AQ DK 2007 0222	1199705	✓
cygoret	Zimmer	-	ACS V22043 64	-	✓
Alexto combi	Alexandria	Alexandria	IALTA 22010009D	1,391,570	X

Report:

- The Flash lamp of combi was broken
- The Aiming beam was burned

Actions:

- I change flash lamp

Price: \$2000 ~~dis~~ → \$1500

Engineer name & signature:

Customer Name & signature