

Date:

18-12-2024

Report Type:

Maintenance

Customer:

Name: Dr. Shelan	Location: Sul
------------------	---------------

Machine:

Name: motus Ax 2	Type: Alexandrite
Model: M112A1	Serial No.: QM214102

Inspection:

Lamp shots: 1,778,853	Conductivity: 0.745
Rod shots: 17,350,278	Lenses: ok
Lamps No.: 8	Main shape: ok
Moveo use: 38%	Water leak: ok
Photod.: External 49 J Internal 49 J	Electrical & Hydraulic parts: ok
Results (phtod. & peltier)%: 1.1	Power
Fiber test: ok	Before replacement: 30.6 = 540
	After replacement: 30.6 = 480
Alarms: low energy + Simmer	

Report:


low energy more than 5 times

Actions:

I change flash lamp

Cost: \$2000 → \$1400

Engineer name & signature:



Customer Name & signature

Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square

Senior Engineer: Siyamend Alsino, 07514343415 - 07828386448