

Date:

Report Type:

2024/11/21 maintenance

Customer:

Name: Dr. Shaker Ibrahim	Location: ...
--------------------------	---------------

Machine:

Name: Hair Beam 3	Type: Alex
Model: Motex Ax	Serial No.:

Inspection:

Lamp shots:	Conductivity: —
Rod shots:	Lenses: <input checked="" type="checkbox"/>
Lamps No.:	Main shape: <input checked="" type="checkbox"/>
Moveo use:	Water leak: <input checked="" type="checkbox"/>
Photod.: External Internal	Electrical & Hydraulic parts: <input checked="" type="checkbox"/>
Results (phtod. & peltier)%:	Power Before replacement:
Fiber test:	After replacement:
Alarms: low power	

Report:
 ...
 ...

Actions:
 ...
 ...

Cost: \$2125 → \$1500

Engineer name & signature:

Customer Name & signature

[Signature]

[Signature]