

Date:

Report Type:

2024/10/27

Maintenance

**Customer:**

|                         |                      |
|-------------------------|----------------------|
| Name: <u>Jarag Has.</u> | Location: <u>Sul</u> |
|-------------------------|----------------------|

**Machine:**

|  |                   |
|--|-------------------|
| Name: <u>Hair Remov</u> <input type="checkbox"/> | Type: <u>Alex</u> |
| Model: <u>motor Alex</u>                         | Serial No.:       |

**Inspection:**

|  |  |
|--|--|
| Lamp shots: <u>5,427,110</u>                 | Conductivity: <u>31</u>                |
| Rod shots: <u>27,426,043</u>                 | Lenses: <u>α</u>                       |
| Lamps No.: <u>4</u>                          | Main shape: <u>✓</u>                   |
| Moveo use: <u>1</u>                          | Water leak: <u>✓</u>                   |
| Photod.: External <u>—</u> Internal <u>—</u> | Electrical & Hydraulic parts: <u>α</u> |
| Results (phtod. & peltier)%: <u>0.5</u>      | Power                                  |
| Fiber test: <u>✓</u>                         |  |
| Alarms: <u>Laser slow</u>                    | After replacement: <u>-</u>            |

**Report:**

تعمیرات انجام شده و دستگاه به حالت عادی درآید

توجه: تمام قطعات الکتریکی

**Actions:**

تعمیرات انجام شده و دستگاه به حالت عادی درآید

توجه: تمام قطعات الکتریکی

**Cost:** \$125 <sup>د.3</sup> ⇒ \$100

Engineer name & signature:

*[Signature]*

Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Customer Name & signature

*[Signature]*

Main Office: Erbil, Mahmood Alhafeed Square