

Date:

14-10-2024

Report Type:

Maintenance

**Customer:**

Name: Hawkey Kurdistan	Location: Sul
------------------------	---------------

**Machine:**

Name: Hair Removal <input checked="" type="checkbox"/>	Type: Alex
Model: Motus AX	Serial No.:

**Inspection:**

Lamp shots: 3938,704	Conductivity: 1.4 uS
Rod shots: 14,245,801	Lenses: ok
Lamps No.: 3	Main shape: ok
Moveo use: 99%	Water leak: not ok
Photod.: External — Internal —	Electrical & Hydraulic parts: ok
Results (phtod. & peltier)%: 1.1%	Power
Fiber test: on	
	After replacement: —
Alarms: water level	

**Report:**

water level there was water leak


**Actions:**

I change connector for water

**Cost:**

8350 dis → 8250

Engineer name & signature:



Customer Name & signature

