

Date: 2024/12/11

Report Type: Maintenance

Customer:

Name: Dr. Shw Babakasal Location: sul

Machine:

Name: Hair Remol Type: Alex
Model: Zenith Serial No.:

Inspection:

Lamp shots: 782,886	Conductivity: -	
Rod shots: 3,949,985	Lenses: ✓	
Lamps No.: -	Main shape: ✓	
Moveo use: -	Water leak: ✓	
Photod.: External - Internal -	Electrical & Hydraulic parts: α	
Results (phtod. & peltier)%: -	Power	
Fiber test: ✓		Before replacement: -
		After replacement: -
Alarms: Flow switch - No flow		

Report:

شماره خطی: 782,886
شماره میله: 3,949,985
تست فیبر: ✓
تست پلیر: -
تست لامپ: -
تست آب: ✓
تست الکتریکی و هیدرولیک: α

Actions:

1- تعویض لامپ
2- تعویض میله
3- تعویض فیبر

Cost: \$ 950 ^{dis} → \$ 850

Engineer name & signature:

[Signature]

Customer Name & signature

[Signature]

Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square