

Date: 2024/11/7 Report Type: Maintenance

Customer:

Name: C. Pakow Z Location: Kerkuk

Machine & Inspection:

Name	Type	Model	Serial Number	Lamp Shoots	✓ / ✗
-	-	-	-	-	-
Hair Remd	Alex	Combi	TA17A22030016	400,000	✗

Report:

- One of the flash lamp was broken.

Actions:

- I replaced the flash lamp. (1)

Price: \$500 dis → \$400.

Engineer name & signature:

[Signature]

Customer Name & signature

[Signature]

Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad, Diyala)

Main Office: Erbil, Mahmood Alhafeed Square