WORLD GATE
Medical & Lab. Supplies

Report

No: 011439

Date: 3-11-2024

Report Type: Maintenance

Customer:

Name: Dr. Ayob	Location: SUL

Machine & Inspection:

Name	Type	Model	Serial Number	Lamp Shoots	✓ / ✗
Alesthei combi	Alex	Combi	JA1A2411000 2	1414511	X

Report:

There was water leak from the rod

Actions:

we fix the water leak

Price:

Engineer name & signature:

Customer Name & signature