

Date:

2024/11/14

Report Type:

mainten

Customer:

Name: Dr. Sadi Kalil	Location: Halabja
----------------------	-------------------

Machine:

Name: Hair Removal <input type="checkbox"/>	Type: A led
Model: motor Ax	Serial No.:

Inspection:

Lamp shots: 4,217, 628	Conductivity: 1,3
Rod shots: 31, 700, 171	Lenses: ✓
Lamps No.: 7	Main shape: ✓
Moveo use: 99%	Water leak: ✓
Photod.: External - Internal -	Electrical & Hydraulic parts: ✓
Results (phtod. & peltier)%:	Power Before replacement:
Fiber test: ✓	Power After replacement:
Alarms: water level	

Report:

1- Rod HR 300 و 200
2- HR 300 و 200

Actions:

3- HR 300 و 200

Cost: \$ 300 ⇒ 200

Engineer name & signature:

Customer Name & signature

[Signature]

[Signature]

Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square