

Date:

2024/11/11

Report Type:

Maintenance

Customer:

Name: Parillon C	Location: Sul
------------------	---------------

Machine:

Name: Hair Band <input type="checkbox"/>	Type: Alex
Model: Motor Da	Serial No.:

Inspection:

Lamp shots: 4,139,579	Conductivity: 1.3 MS
Rod shots: 6102211	Lenses: ok
Lamps No.: 4	Main shape: ok
Moveo use: 0%	Water leak: ok
Photod.: External 498 Internal 498	Electrical & Hydraulic parts: ✓
Results (phtod. & peltier)%: 300	Power
Fiber test: ok	
Alarms: low energy	After replacement: 30,6 = 490

Report:

The Power of machine was low


Actions:

I change Flash lamp


Cost:

82000 dis → 1400

Engineer name & signature:



Customer Name & signature



Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square