

report

No.: 016395

Date:

16-11-2024

Report Type:

check

Customer:

Name: Dr. Sener

Location: Sul

Machine:

Name: Light Age

Type: Alexandrite

Model: Update

Serial No.: Sol-16-666-LP*

Inspection:

Lamp shots: 576.925

Conductivity:

Rod shots: 576.925

Lenses: not ok

Lamps No.: 1

Main shape: ok

Moveo use: —

Water leak: ok

Photod.: External ok Internal ok

Electrical & Hydraulic parts: ok

Results (phtod. & peltier)%: —

Fiber test: ok

Power Before replacement: ok

Alarms: no Alarm

Power After replacement: —

Report:

There was lens damaged

Actions:

I change lens 504-1700-10

Cost: 8400 → 8360

Engineer name & signature:

Customer Name & signature

Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square

Senior Engineer: Siyamend Alsino, 07514343415 - 07828386448