

Date:

06-01-2025

Report Type:

Maintenance

Customer:

Name: Center Jenu	Location: Ramia
-------------------	-----------------

Machine:

Name: Hair Remover <input type="checkbox"/>	Type: Alexandrite
Model: Zenith	Serial No.: 504-21-0790-ZHA

Inspection:

Lamp shots: 15873240	Conductivity: —
Rod shots: 375484	Lenses: OK
Lamps No.: 3	Main shape: OK
Moveo use: —	Water leak: OK
Photod.: External 408 Internal 40 J	Electrical & Hydraulic parts: OK
Results (phtod. & peltier)%: —	Power
Fiber test: OK	
Alarms: Low Power	After replacement: 3500 D _d = 40 J


Report:

1- Low Power 3- The fiber has some spot
2- Pump chamber


Actions:

1- I change Flush lamps
2- The Pump chamber maybe need to be changed
3- Protection lens (3)

Cost: _____



Engineer name & signature:



Customer Name & signature