



Date:

2023/1/14

Report Type:

Maintenance

Customer:

Name: Dr. Gener	Location: Sul
-----------------	---------------

Machine:

Name: H.R	<input checked="" type="checkbox"/>	Type: Alax
Model: Zenith		Serial No.:

Inspection:

Lamp shots: 2,323,114	Conductivity: -
Rod shots: 3,805,680	Lenses: X
Lamps No.: 2	Main shape: ✓
Moveo use: -	Water leak: ✓
Photod.: External - Internal -	Electrical & Hydraulic parts: ✓
Results (phtod. & peltier)%: -	Power
Fiber test: ✓	Before replacement: -
Alarms: Simmer Detect	After replacement: -

Report:

- The power is low
- There is lens code 8000-20A has spot we will check when needed

Actions:

I change flush lamp p. ②

Cost: \$2,500

Customer Name & signature

Engineer name & signature:

[Signature]

[Signature]

Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square

Senior Engineer: Siyamend Alsino, 07514343415 - 07828386448