

Date:

2025/1/17

Report Type:

Maintenance

Customer:

Name: Dr. Sadi	Location: Halabja
----------------	-------------------

Machine & Inspection:

Name	Type	Model	Serial Number	Lamp Shoots	✓/✗
Cozleser	Coz	smcd.1	AME 2011 0959	-	✓

Report:

Graphic board was damaged.

Actions:

I change it

Price:


\$600

Engineer name & signature:



Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad, Diyala)

Customer Name & signature



Main Office: Erbil, Mahmood Alhafeed Square